

Tips Before Starting

- Ensure the surface is dry, clean (polish first if needed) and dust free.
- Read through instructions before starting
- Two **light** coats should suffice; the first coat should be applied in a top-to-bottom fashion. The second coat should be applied side-to-side; waiting approximately 20 minutes between coats.

Application Directions

- 1. Ensure that the surface is free of dirt, grease, wax and grime.
- 2. Shake well allow agitator to rattle for at least two minutes.
- 3. For best results, use when temperature is between 65°F and 95°F. Avoid using during high humidity.
- 4. Holding the can approximately 10 inches from the surface, <u>depress the valve completely</u> to avoid reduced pressure, resulting in faulty spray.
- 5. To prevent sags and runs, use short dusting strokes allowing Incralac to become tacky between light mist coats.
- 6. To prevent clogging, <u>clean nozzle after each use</u>. Invert can and spray approximately three seconds until mist becomes clear.
- 7. Discard empty can in trash pick-up. <u>Do not</u> place in garbage compactor.